

## CLUTCH RELEASE ISSUE– HOLDEN / ISUZU

The slave cylinder in these vehicles is fitted with a solenoid that regulates the flow of hydraulic fluid to and from the master cylinder.

It is recommended to inspect the hydraulic system to ensure that the slave cylinder is not holding line pressure. The clutch slave cylinder solenoid in these units can fail causing irregular fluid displacement.



A faulty slave cylinder will impact the functionality of the clutch and may result in premature failure, slip or non release.