

TRANSPORTATION LOCK REMOVAL

Clutch Kit Number – PDK42774

Vehicle Application – Holden Barina/Combo XC Z14XE

The Concentric Slave Cylinder included in this clutch kit has a **RED** transportation lock fitted to it.

After installing the CSC to the transmission housing using the correct tightening torque settings found in the manufacturers manual, this red lock must be removed.



Failure to do so will cause damage to the CSC when the transmission is installed